

HAER  
ORE,  
3-621N  
1A-

## HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

Willamette Falls Lock  
Chamber #1  
West Linn, Oregon  
Clackamas County

Robert Heims, Photographer 1980

- OR-1-1 VIEW OF BASALT ROCK FORMATION BEHIND WEST WALL OF LOCK CHAMBER NO. 1--June 1980
- OR-1-2 VIEW OF EAST WALL OF LOCK CHAMBER NO. 1--- Photo taken from lock gate No. 2, looking northeast, June 1980
- OR-1-3 VIEW OF WEST WALL OF LOCK CHAMBER NO. 1--Photo taken from east wall looking west; Lock Gate No. 2 in background, part of Lock Gate No. 1 on the right--June 1980
- OR-1-4 VIEW OF WEST WALL OF LOCK CHAMBER NO. 1 FROM EAST WALL LOOKING WEST--June 1980
- OR-1-5 VIEW OF EAST WALL OF LOCK CHAMBER NO. 1 LOOKING SOUTHEAST TOWARDS LOCK GATE NO. 2, FROM UNDER WEST WALKWAY--June 1980
- OR-1-6 GENERAL VIEW OF LOCK CHAMBER NO. 1 FROM AREA ABOVE WEST WALL LOOKING SOUTHEAST--August 1980, during repairs
- OR-1-7 VIEW OF WEST WALL LOOKING DOWNSTREAM AND NORTH FROM LOCK GATE NO. 2--August 1980, during repairs
- OR-1-8 VIEW OF WEST WALL LOOKING SOUTHWEST; LOCK GATE NO. 2 IN BACKGROUND--August 1980, during repairs
- OR-1-9 VIEW OF WEST (left) AND EAST (right) WALLS, LOOKING NORTH WITH COFFER DAM IN BACKGROUND--August 1980, during repairs
- OR-1-10 GENERAL VIEW OF LOCK CHAMBER NO. 1 LOOKING SOUTH SHOWING LOCK GATE NO. 2 IN BACKGROUND--September 1980, during repairs
- OR-1-11 GENERAL VIEW OF LOCK CHAMBER NO. 1 LOOKING NORTH, FROM LOCK GATE NO. 2-- October 1980, after repairs

- OR-1-12      GENERAL VIEW OF EAST WALL LOOKING SOUTHEAST FROM  
              AREA ABOVE WEST WALL--October 1980, after repairs
- OR-1-13      GENERAL VIEW OF LOCK CHAMBER NO. 1 LOOKING SOUTH  
              SHOWING EAST WALL AND WALKWAY ABOVE WEST WALL, WITH  
              LOCK GATE NO. 2 IN BACKGROUND--October 1980, after  
              repairs
- OR-1-14      VIEW OF WEST WALL AND WALKWAY LOOKING NORTHWEST FROM  
              EAST WALL--October 1980, after repairs